

AD-A097 980


ROCK ISLAND ARSENAL IL ENGINEERING DIRECTORATE
COATING OF STEEL PISTONS WITH BEARING MATERIALS. PHASE 1. (U)

F/G 11/3

OCT 80 M SOLANKI

UNCLASSIFIED SARRI-EN-81-01

NL



AD A 097980

The image shows the U.S. Army Air Forces insignia, which consists of a shield with a stylized 'V' or 'W' shape, a white star in the upper left corner, and the word 'AMERICA' curved along the bottom. The shield is mounted on a flagpole. The entire emblem is rendered in black and white.

COATING OF WEAPON COMPONENTS WITH BEARING MATERIAL (Phase 1)

M.SOLANKI

DECEMBER 1980

APR 21 1981

A

TECHNICAL REPORT

ENGINEERING DIRECTORATE

DISTRIBUTION STATEMENT

Approved for public release; distribution unlimited.

DMC FILE COPY

**ROCK ISLAND ARSENAL
ROCK ISLAND, ILLINOIS 61299**

81420070

DISPOSITION INSTRUCTIONS:

Destroy this report when it is no longer needed. Do not return it to the originator.

DISCLAIMER:

The findings of this report are not to be construed as an official Department of the Army position unless so designated by other authorized documents.

Unclassified
SECURITY CLASSIFICATION OF THIS PAGE (When Data Entered)

REPORT DOCUMENTATION PAGE			READ INSTRUCTIONS BEFORE COMPLETING FORM
1. REPORT NUMBER EN-81-01 ✓	2. GOVT ACCESSION NO. AD-HC97980	3. RECIPIENT'S CATALOG NUMBER	
4. TITLE (and Subtitle) Coating of Steel Pistons with Bearing Materials (Phase 1)		5. TYPE OF REPORT & PERIOD COVERED Technical Report	
6. PERFORMING ORG. REPORT NUMBER 10, Mukesh/Solanki		7. CONTRACT OR GRANT NUMBER(S) SARRI-L-1-21 41	
8. PERFORMING ORGANIZATION NAME AND ADDRESS Commander Rock Island Arsenal Rock Island, IL 61299		9. PROGRAM ELEMENT, PROJECT, TASK AREA & WORK UNIT NUMBERS AMS Code 4932.06.8035	
10. CONTROLLING OFFICE NAME AND ADDRESS Commander Rock Island Arsenal, SARRI-EN Rock Island, IL 61299		11. REPORT DATE October 1980	
12. MONITORING AGENCY NAME & ADDRESS (if different from Controlling Office)		13. NUMBER OF PAGES 29	
14. DISTRIBUTION STATEMENT (of this Report) Approved for public release; distribution unlimited.		15. SECURITY CLASS. (of this report) Unclassified	
16. DISTRIBUTION STATEMENT (of the abstract entered in Block 20, if different from Report)		17a. DECLASSIFICATION/DOWNGRADING SCHEDULE	
18. SUPPLEMENTARY NOTES			
19. KEY WORDS (Continue on reverse side if necessary and identify by block number) 1. Nodular iron 2. Steel 3. Al-bronze 4. Toughness 5. GMAW (Gas Metal Arc Weld) 6. Wear			
20. ABSTRACT (Continue on reverse side if necessary and identify by block number) Nodular iron pistons for the M174 Recoil Mechanism characteristically yield less-than-desirable service lives; the deficiency being attributed to a lack of fracture toughness of the iron. Consequently, cast steel pistons clad with a bearing material, required since the steel does not offer the built-in lubricity indigenous to nodular iron, were considered as an alternate material. Cost-effective Gas Metal Arc Welding (GMAW) processing techniques were developed to provide an aluminum-bronze bearing surface to the steel pistons. Concurrent			

DD FORM 1 JAN 73 1473 EDITION OF 1 NOV 68 IS OBSOLETE

Unclassified
SECURITY CLASSIFICATION OF THIS PAGE (When Data Entered)

Unclassified

SECURITY CLASSIFICATION OF THIS PAGE(When Data Entered)

laboratory tests were conducted on welded specimens to simulate live-firing performance. The tests included chemical, mechanical and metallurgical analyses. After development of the GMAW procedure, including selection of an aluminum-bronze bearing material, a coated steel piston was manufactured at Rock Island Arsenal and subjected to firing tests. Its performance in the Arsenal simulator followed by live-firing at Yuma Proving Ground exceeded all requirements.

Future studies will provide more clad steel pistons for firing tests to verify material performance. In addition, strip welding and explosive bonding methods will be evaluated to determine the least cost method of cladding steel components with aluminum-bronze.

ii Unclassified

SECURITY CLASSIFICATION OF THIS PAGE(When Data Entered)

FOREWORD

The work was authorized as part of the Manufacturing Methods and Technology Program of the U.S. Army Materiel Development and Readiness Command and was administered by the U.S. Army Industrial Base Engineering Activity.

Accession No.	
1	2
3	4
5	6
7	8
9	10
11	12
13	14
15	16
17	18
19	20
21	22
23	24
25	26
27	28
29	30
31	32
33	34
35	36
37	38
39	40
41	42
43	44
45	46
47	48
49	50
51	52
53	54
55	56
57	58
59	60
61	62
63	64
65	66
67	68
69	70
71	72
73	74
75	76
77	78
79	80
81	82
83	84
85	86
87	88
89	90
91	92
93	94
95	96
97	98
99	100
101	102
103	104
105	106
107	108
109	110
111	112
113	114
115	116
117	118
119	120
121	122
123	124
125	126
127	128
129	130
131	132
133	134
135	136
137	138
139	140
141	142
143	144
145	146
147	148
149	150
151	152
153	154
155	156
157	158
159	160
161	162
163	164
165	166
167	168
169	170
171	172
173	174
175	176
177	178
179	180
181	182
183	184
185	186
187	188
189	190
191	192
193	194
195	196
197	198
199	200
201	202
203	204
205	206
207	208
209	210
211	212
213	214
215	216
217	218
219	220
221	222
223	224
225	226
227	228
229	230
231	232
233	234
235	236
237	238
239	240
241	242
243	244
245	246
247	248
249	250
251	252
253	254
255	256
257	258
259	260
261	262
263	264
265	266
267	268
269	270
271	272
273	274
275	276
277	278
279	280
281	282
283	284
285	286
287	288
289	290
291	292
293	294
295	296
297	298
299	300
301	302
303	304
305	306
307	308
309	310
311	312
313	314
315	316
317	318
319	320
321	322
323	324
325	326
327	328
329	330
331	332
333	334
335	336
337	338
339	340
341	342
343	344
345	346
347	348
349	350
351	352
353	354
355	356
357	358
359	360
361	362
363	364
365	366
367	368
369	370
371	372
373	374
375	376
377	378
379	380
381	382
383	384
385	386
387	388
389	390
391	392
393	394
395	396
397	398
399	400
401	402
403	404
405	406
407	408
409	410
411	412
413	414
415	416
417	418
419	420
421	422
423	424
425	426
427	428
429	430
431	432
433	434
435	436
437	438
439	440
441	442
443	444
445	446
447	448
449	450
451	452
453	454
455	456
457	458
459	460
461	462
463	464
465	466
467	468
469	470
471	472
473	474
475	476
477	478
479	480
481	482
483	484
485	486
487	488
489	490
491	492
493	494
495	496
497	498
499	500
501	502
503	504
505	506
507	508
509	510
511	512
513	514
515	516
517	518
519	520
521	522
523	524
525	526
527	528
529	530
531	532
533	534
535	536
537	538
539	540
541	542
543	544
545	546
547	548
549	550
551	552
553	554
555	556
557	558
559	560
561	562
563	564
565	566
567	568
569	570
571	572
573	574
575	576
577	578
579	580
581	582
583	584
585	586
587	588
589	590
591	592
593	594
595	596
597	598
599	600
601	602
603	604
605	606
607	608
609	610
611	612
613	614
615	616
617	618
619	620
621	622
623	624
625	626
627	628
629	630
631	632
633	634
635	636
637	638
639	640
641	642
643	644
645	646
647	648
649	650
651	652
653	654
655	656
657	658
659	660
661	662
663	664
665	666
667	668
669	670
671	672
673	674
675	676
677	678
679	680
681	682
683	684
685	686
687	688
689	690
691	692
693	694
695	696
697	698
699	700
701	702
703	704
705	706
707	708
709	710
711	712
713	714
715	716
717	718
719	720
721	722
723	724
725	726
727	728
729	730
731	732
733	734
735	736
737	738
739	740
741	742
743	744
745	746
747	748
749	750
751	752
753	754
755	756
757	758
759	760
761	762
763	764
765	766
767	768
769	770
771	772
773	774
775	776
777	778
779	780
781	782
783	784
785	786
787	788
789	790
791	792
793	794
795	796
797	798
799	800
801	802
803	804
805	806
807	808
809	810
811	812
813	814
815	816
817	818
819	820
821	822
823	824
825	826
827	828
829	830
831	832
833	834
835	836
837	838
839	840
841	842
843	844
845	846
847	848
849	850
851	852
853	854
855	856
857	858
859	860
861	862
863	864
865	866
867	868
869	870
871	872
873	874
875	876
877	878
879	880
881	882
883	884
885	886
887	888
889	890
891	892
893	894
895	896
897	898
899	900
901	902
903	904
905	906
907	908
909	910
911	912
913	914
915	916
917	918
919	920
921	922
923	924
925	926
927	928
929	930
931	932
933	934
935	936
937	938
939	940
941	942
943	944
945	946
947	948
949	950
951	952
953	954
955	956
957	958
959	960
961	962
963	964
965	966
967	968
969	970
971	972
973	974
975	976
977	978
979	980
981	982
983	984
985	986
987	988
989	990
991	992
993	994
995	996
997	998
999	1000

TABLE OF CONTENTS

DD FORM 1473	i
FOREWORD	iii
TABLE OF CONTENTS	iv
LIST OF TABLES	v
LIST OF FIGURES	vi
1.0 INTRODUCTION	1
1.1 GMAW Welding (Phase 1)	1
1.2 Strip Cladding (Phase 2)	2
2.0 MECHANICAL, CHEMICAL AND METALLURGICAL ANALYSES:	2
2.1 Chemical Analysis	2
2.2 Hardness Analysis	3
2.3 Friction Wear Tests	4
2.3.1 Test Apparatus	4
2.3.2 Specimen Fabrication	4
2.3.3 Test Procedure	4
2.3.4 Results and Discussion	5
2.4 Shear and Tensile Test	5
2.4.1 Procedure	5
2.4.2 Results	5
2.5 Metallographic Analysis	5
3.0 WELDING PROCEDURE FOR STEEL PISTONS	8
3.1 Welding Parameters	8
4.0 FIRING TESTS AND ANALYSES	9
4.1 Simulation Test and Analysis	9
4.2 Live-Firing Test and Analysis	9
5.0 CONCLUSIONS	9
6.0 RECOMMENDATIONS	10
7.0 FUTURE WORK	10

LIST OF TABLES

TABLE 1 - CHEMICAL COMPOSITION	3
TABLE 2 - HARDNESS SURVEYS OF OVERLAYERED STEEL PLATE	3
TABLE 3 - RESULTS OF FRICTION AND WEAR TESTS	6

LIST OF FIGURES

1 - FRICTION & WEAR TEST SPECIMENS	11
2 - SHOWING WEAR ON SURFACES AFTER ONE-HOUR TESTS	12
3 - DIMENSIONS FOR SHEAR AND TENSILE TEST SPECIMENS	13
4 - SPECIMENS BEFORE AND AFTER TESTS	14
5 - MICROGRAPHS SHOWING COPPER-RICH DENDRITES IN AL-BRONZE OVERLAY	15
6 - HEAT AFFECTED ZONE CONSISTS OF BAINITE AND FERRITE STRUCTURES	16
7 - CROSS SECTIONAL VIEW OF RECOIL PISTON FOR M174 GUN MOUNT, COATED WITH BEARING MATERIAL	17
8 - OVERALL SET UP FOR OVERLAYING AL-BRONZE ON M174 RECOIL PISTON USING GMAW PROCESS	18
9 - ILLUSTRATION OF TORCH POSITION LOOKING FROM REAR OF PISTON	19
10 - M174 PISTON COATED WITH AL-BRONZE (UNFINISHED)	20
11 - CROSS SECTIONAL VIEW OF M174 PISTON, COATED WITH AL-BRONZE ON O.D. AND I.D. SURFACE	21
12 - LIGHT SCORING ON OUTER BEARING SURFACE OF M174 PISTON	22
13 - LIGHT SCORING ON INNER BEARING SURFACE OF M174 PISTON	23
14 - LINEAR SCRATCHES ON CHROMIUM PLATED SURFACE OF RECOIL CYLINDER	24

1.0 INTRODUCTION:

The objective of this project is to develop cost effective manufacturing methods to coat weapon components with bearing materials for improved performance. The first phase of the work was directed to the manufacture of a steel piston for the M174 Recoil Mechanism which is not prone to failure by fracture of the piston body and which exhibits significantly greater bearing wear life when compared to the one-piece cast nodular piston currently in use. The use of nodular iron in production has been desirable since its microstructure offers "built-in" lubricity. However, the attainment of a homogeneous microstructure is most difficult and, if possible, very costly when casting non-uniform wall thicknesses typical of the piston. Therefore, low alloy steel was substituted for the nodular iron to impart adequate performance characteristics to the piston.

The use of steel for pistons dictates that a bearing material must be applied to surfaces since the steel does not afford the built-in lubricity of nodular iron. Several methods to coat the steel with bearing materials, e.g., flame spray, arc spray, etc., have been used. Sprayed castings may have an inherent advantage, i.e., they are less than fully dense (approximately 20 - 25% porosity) after being applied to the substrate and this might impart some self-lubricating quality to the material. However, this possible advantage is far outweighed by the coatings having low adhesive strengths (generally less than 1,000 psi), and being subject to brittle failure because of the formulation of oxide layers on metal particles. The oxide layers formed make surfaces hard and abrasive thereby reducing the bearing quality of the material. Consequently, their function as bearing materials is quite limited. In addition, the application of sprayed coatings to the inner diameter surfaces of certain components is often inhibited by the space available. That is, proper tool-to-workpiece distances are not possible when coating interior surfaces. It is, therefore desirable to define improved methods to coat pistons with bearing materials. The following are methods to be evaluated in Phase 1 and Phase 2.

1.1 GMAW Welding: (Phase 1)

The use of Gas Metal Arc Welding (GMAW) methods to apply bronze bearing materials to inner and outer surfaces of the pistons was investigated. The reasons for its selection are attributed to its high bond strength (equivalent to the yield strength of the material) and very low porosity and oxide contamination when compared to flame and arc sprays. As the bearing material is welded to the substrate, the mechanically-bonded interface typical of sprayed metals is eliminated; hence, highest interface strengths are available. Also, automation of the welding operation is possible, thereby reducing process variables. The primary caution is concerned with the avoidance of a complete reheat treatment being required after welding. This is accomplished by minimizing the effects of high localized heat-input to the metallurgical condition of the steel, i.e., by adapting adequate cooling methods and by interrupting the welding process at required intervals.

1.2 Strip Cladding: (Phase 2)

The use of strip cladding (modified submerged arc welding) methods to apply thin metal strip rather than wire to substrates will be investigated in Phase 2. This process is characterized by high deposition rates, i.e., 40-55 lbs/hr, when compared to GMAW welding processes which characteristically deposit approximately 20-25 lbs/hr or metal arc spray methods which impart about 25 lbs/hr. Because of the lower heat input and lower dilution of filler metal and substrate, post heat treatment requirements are further minimized. In addition, the strip cladding procedures are more amenable to automation techniques. Some development of the strip cladding process is required before it can be used, therefore, it was decided to use state-of-the-art GMAW methods for the Phase 1 study.

2.0 MECHANICAL, CHEMICAL AND METALLURGICAL ANALYSES:

To evaluate important properties of bearing material and processes of cladding by simulation and live firing tests would be difficult and very expensive. Consequently, chemical, hardness, wear and friction, tensile and shear (bond) strength test and metallographic analyses were conducted in the laboratory. These tests were carried out for better understanding of material performance.

A low alloy steel plate (20" x 12" x 0.5") was clad with Al-Bronze (Ampco-trode 46) using the following welding parameters:

Voltage: 28-29 V
Current: 260-300 amp
Slope: Flat
Travel speed: 20 in/min
Shielding Gas/Flow Rate: Argon/35 CFH
Cooling: Water spray
Preheat: None

After being coated with Al-Bronze, the test plate was tempered at 1000°F for 2 hours. Various specimens were then machined for laboratory testing.

2.1 Chemical Analysis:

Chemical composition of steel plate was determined by using optical emission spectrographic techniques and chemical analyses of filler wire and the clad deposit was accomplished by wet chemical analysis. The chemical composition of the bearing alloy and steel substrate are presented in Table 1.

TABLE 1
CHEMICAL COMPOSITION
Chemical elements (weight %)

Steel Substrate

C	Si	Cu	Mn	Ni	V	P	Cr	S	Mo	Fe
0.287	0.304	0.125	0.518	0.065	0.003	0.0011	0.983	0.0123	0.221	Balance

Ampco-trode 46 (filler wire)

Cu	Ni	Fe	Al	Mn	Zn	Sn	Pb	Si
81.2	4.3	4.1	9.1	1.08	0.006	0.04	0.002	0.03

Clad Deposit

Cu	Ni	Fe	Al	Mn	Zn	Sn	Pb	Si	Other
76.4	3.8	7.2	8.9	1.02	.005	0.06	0.003	0.06	2.5

During weld cladding operations, it is desired to minimize dilution of the deposit. If the iron content in the deposit exceeds 10%, then a hard, iron-rich phase is formed that reduces the bearing quality of the coated surface. But by using filler wire of proper chemical composition and adequate cooling, it is observed that the iron content in the deposit was limited to 7.2%.

2.2 Hardness Analysis:

Hardness determination of test steel plate is presented in Table 2. As desired, the hardness of the bearing material was about 50 points Brinell lower than the steel substrate.

TABLE 2
HARDNESS SURVEYS OF OVERLAYERED STEEL PLATE

Bearing Material (Ampco-trode 46)	Hardness 231 - 244 KHN (216 - 232 BHN)
Steel Substrate (QQ-S-681, Grade 4)	Hardness 27 - 28 RC (265 - 271 BHN)

2.3 Friction Wear Tests:

2.3.1 Test Apparatus: The friction and wear properties of the bearing materials were determined using the Alpha LFW-3 Tester. The flat surface of a rotating annular ring is used in this machine to give area contact against a stationary flat surface. The apparent area contact can be varied by a change in the diameter or width of the annular ring. Bearing pressures with standard specimens vary from 400 to 20,000 psi and this can be increased by a reduction in the area of contact. Speeds are infinitely variable from 1.47 to 52.3 fpm, and oscillatory motion is possible from 6 to 227 cycles per minute (cpm). The machine is designed for testing dry or liquid lubricants in various atmospheres and at temperatures from room temperature to 1,200°F. A single channel recorder was used for continuous recording of frictional force. Temperature measurement was done by Heat-Prober Thermometer.

2.3.2 Specimen Fabrication: The bearing materials were machined to form the stationary disc specimens. The wearing surface of the specimens was prepared on a table grinder to 14 rms finish. Final dimensions of bearing disc are shown in Figure 1a.

The mating material (4130 steel) was machined to form the oscillatory ring specimens. The wearing surface of these specimens was surface ground to a 20 rms finish. Final dimensions of the steel ring are shown in Figure 1b.

2.3.3 Test Procedure: The LFW-3 specimens, when initially received from the machine shop, were wiped and sprayed with naptha petroleum solvent. Before and after each LFW-3 test, the specimens were washed consecutively in methanol and petroleum ether. The specimens were blown dry and weighed.

Initially, the bearing and the mating test specimens were weighed to the nearest 0.1 mg. The specimens were then mounted in their respective positions and covered with hydraulic fluid (MIL-H6083D). The LFW-3 test conditions were those involving a 120° angle of oscillation at a frequency of 120 cycles per minute (64 inch per second linear velocity). The tests were conducted for durations of 10 and 60 minutes. The pressure during the first 60 seconds was 200 lbs/in² and was followed over the next 60 seconds by an increase in load to pre-set pressures of 500, 1000 or 1500 lbs/in².

The variables measured in each LFW-3 test were co-efficients of friction (μ_f), friction generated temperature (T), and total wear. The initial co-efficients of friction (μ_f initial) were determined immediately after full load was reached. Final co-efficients of friction (μ_f final) were determined just before the end of the test period. The temperature of the hydraulic fluid covering the wear specimens was monitored continuously.

After completion of the test, both the mating and bearing LFW-3 specimens were visually examined, and the weight loss or gain of each was determined. The visual examination consisted of inspection for evidence of discoloration, type of wear and metal transfer.

2.3.4 Results and Discussion:

Under all experimental conditions used, the co-efficient of friction for Al-Bronze is twice that of nodular iron (see Results, Table 3). It was observed that for the shorter time duration test (1 min.), nodular iron shows less wear than Al-Bronze. But for the one hour test at higher load (1500 lbs), the nodular iron surface and mating steel surface experienced severe galling (Figure 2a), whereas under the same experimental conditions the Al-Bronze surface revealed medium galling (Figure 2b). A possible explanation for this is that under higher loads for long time, graphite particles imbedded in the nodular iron matrix are gradually eroded from the surface causing the material to lose its natural lubricity.

2.4 Shear and Tensile Test:

2.4.1 Procedure: The particular tensile/shear test specimen design is used to measure bond strength in shear and also tensile strength of cladding materials (see Figure 3).

Both the tensile and shear specimen are pulled in tension. The shear specimen, however, has a smaller interface between the overlay and the substrate. Therefore, a larger shear stress is experienced when the shear specimen receives the same load as the tensile specimen. If the bond strength of the interface in shear is greater than the yield strength of the overlay in tension, then the specimen will fail in the bearing material. If the reverse situation is true, the specimen will fail in shear at the interface region.

2.4.2 Results: In all the tests, failure occurred through the clad material in Figure 4. Measured tensile strengths were between 75 to 94 KSI. This indicates that the bond strength in shear is much higher than the tensile strength of bearing material.

2.5 Metallographic Analysis:

The microstructures of weld deposits on the test plate are shown in Figures 5a and 5b. In Figure 5a, a columnar dendritic freezing pattern is evident in the copper-base weld. Crystals grew with a preferred orientation and the dendrite direction is parallel to the direction of heat flow. The gray interdendrite phase may be untransformed beta (Al_{Cu_3}). This phase is retained on rapid cooling of the weld alloy. Such a structure is typical of as-cast copper alloys and is not harmful. No iron-rich phases were detected using the Scanning Electron Microscope. Nominal number of shrinkage cracks were discovered, depths ranging from 0.003 in. to 0.010 in. Since the weld alloy completely filled and bonded these cracks, they were judged to have produced no harmful effects.

Heat Affected Zone (HAZ) consists of bainite and ferrite structures as shown in Figure 6. These types of microstructures are desirable as they have higher toughness, hence re-heat treatment of component is not required.

TABLE 3
RESULTS OF FRICTION & WEAR TESTS

Test Set	Bearing Disc	Wearing Materials	Friction Co-efficient (μ_f)		Test time (min)	T_{max} (°F)		
			Face Ring	Load Applied (lbs)	Initial (μ_f) _i	Final (μ_f) _f		
1	Ampco-trode 46	4130 steel		500	0.166	0.136	10	190
2	Ampco-trode 46	4130 steel		1000	0.226	0.151	10	280
3	Ampco-trode 46	4130 steel		1500	0.224	0.102	10	300
4	Ampco-trode 46	4130 steel		1500	0.230	0.126	60	400
5	Nodular Iron	4130 steel		500	0.108	0.107	10	180
6	Nodular Iron	4130 steel		1000	0.105	0.097	10	175
7	Nodular Iron	4130 steel		1500	0.099	0.092	10	170
8	Nodular Iron	4130 steel		1500	0.107	0.135	60	460

(Table 3 cont'd next page)

TABLE 3 cont'd
RESULTS OF FRICTION & WEAR TESTS

Test Set	Change in Weight at end of test (mg)		Initial Surface Finish (RMS)		Initial Hardness		Wear Type	
	Bearing Disc	Face Ring	Bearing Disc	Face Ring	Bearing Disc	Face Ring	Bearing Disc	Face Ring
1	-0.04	+0.05	10-14	15-20	22.5 R _C	35 R _C	1VL	1VL
2	-4.91	+0.27	10-14	15-20	22 R _C	34.5 R _C	2VL	1VL
3	-6.72	+0.91	10-14	15-20	22.5 R _C	35 R _C	2H, 5	2M, 3VL, 4
4	-37.05	+0.88	10-14	15-20	22.3 R _C	35 R _C	2M, 5	2M, 3VL, 4
5	-0.32	+0.62	12-16	15-20	97.5 R _B	34 R _B	1VL	1VL
6	-0.14	-0.03	12-16	15-20	98.0 R _B	35 R _B	2VL	1VL
7	-0.16	-0.15	12-16	15-20	99.0 R _B	35 R _B	2M, 4L	2M, 3
8	-125.3	-0.2	12-16	15-20	98.5 R _B	34.5 R _B	2S, 4H	2H, 3S

LEGEND

- 1 - Smooth
- 2 - Galling
- 3 - Transferred Bearing Material
- 4 - Discoloration to blue - gray
- 5 - Discoloration to copper luster
- VL - Very light
- L - Light
- M - Medium
- H - Heavy
- S - Severe

3.0 WELDING PROCEDURE FOR STEEL PISTONS:

Gas metal arc welding of steel pistons was initiated. The aluminum bronze family of alloys was proposed as the bearing material after considering ease of application by welding, toughness in service, and a confirmed history of successful application for use in reducing wear/friction when abraded by dissimilar materials. The particular selection of Ampco-trode 46 was made following the established practice whereby the bearing material should be 50 to 75 points Brinell lower in hardness than the mating surface.

3.1 Welding Parameters:

The following parameters were used in the welding process:

Inner Diameter:

Lathe Speed: 35 sec/rev (19.7 IPM on 3.660 in. O.D.)
Carriage Feed: 0.204 in/rev
Pulse: 36V, 1/6 cycle duration, DCRP
Background, 24V, DCRP
Current: 175-195 Amps
Shielding Gas/Flow Rate: Argon/35 CFH
Water cooled O.D.
Preheat: None

(Max. interpass temperature of body: 300°F, cooled with water spray back up for continuous weld.)

Outer Diameter:

Lathe Speed: 71.45 sec/rev (19.8 IPM on 7.5 in. O.D.)
Carriage Feed: 0.200 in/rev
Pulse: 36V, 1/6 cycle duration, DCRP
Background: 24V, DCRP
Current: 190 Amps
Shielding Gas/Flow Rate: Argon/35 CFH
Air cooled
Preheat: None

(No more than two revolutions were made without interruption for cooling.)

Figure 7 shows the desired dimensions for the Al-Bronze coated M174 Piston. Five test pistons were prepared at Rock Island Arsenal (RIA) for simulation and live firing test. A LINDE wire feeder and ST-9 modified torch plus AIRCO pulse arc power supply was used for welding pistons. The overall set-up of the process is shown in Figure 8.

Figure 9 (a & b) shows the torch position for I.D. and O.D. overlaying. After being coated with Al-Bronze, the pistons were tempered at 1000°F for 2 hours. Inspection of X-ray photographs of the pistons revealed a few minor voids,

less than about 0.094 in., and a material which was relatively free of micro-shrinkage. Window areas showed known defects related to prior weld repair of the steel piston and not related to the overlay. This was not of concern since the window areas were to be removed in final machining.

Figure 10 shows the M174 Piston with the Al-Bronze overlay on the outer diameter. After machining, the finished I.D. and O.D. thicknesses of the overlay were 0.060 in. (Figure 11).

4.0 FIRING TESTS AND ANALYSES:

4.1 Simulation Test and Analysis:

A steel piston clad with Al-Bronze was selected for simulation and live-firing tests. The simulation tests were conducted on a hydraulic gymnasticator at Rock Island Arsenal and a total of 3,025 rounds were fired.

On completion of simulation the gun mount was disassembled and both, piston and cylinder, were thoroughly cleaned and visual examination of surfaces was accomplished.

Bearing surfaces of the I.D. and O.D. of the piston were lightly scored as shown in Figures 12 and 13. This was mainly due to abrasion of hard chromium particles which were chipped off from chromium plated surface of the cylinder. Overall performance of Al-Bronze as bearing material was considered good. Figure 14 reveals few linear scratches on inner surface of cylinder.

4.2 Live-Firing Test and Analysis:

After simulation testing, the piston was then sent to Yuma Proving Ground, AZ for live-firing test where a total of 518 rounds were fired. At the conclusion of the test the recoil mechanism was disassembled and the piston was visually examined. It was observed that no adverse degradation of the piston had occurred. Only a few additional scratches were evident and none of these scratches were of any appreciable depth. The piston is considered in excellent condition for additional testing.

5.0 CONCLUSIONS:

The use of cast steel pistons clad with an aluminum-bronze bearing material will resolve prior failure problems experienced with nodular iron pistons currently used in the M174 recoil mechanism. GMAW of Ampco-trode 46 to cast steel pistons results in a competitively priced clad steel piston with no material/manufacturing deficiencies. For example, the intermetallics formed are minimal and do not degrade material performance, i.e., the bond strength of bearing material and its substrate is over twenty times stronger than conventional electric arc metallized coatings. In addition, subject to high pressure friction tests, the aluminum-bronze coatings have better wear resistance when compared to nodular iron.


Development of suitable GMAW procedures results in the cladding of an improved steel piston wherein the dilution of the aluminum-bronze bearing material with iron is kept well below critical levels. Consequently, the quality of the bearing material is maintained. Control of welding parameters and inter-pass temperatures eliminate re-heat treatment requirements since the bulk temperature of the steel substrate does not exceed the tempering temperature of 1100°F. In those areas at the interface where melting occurs, subsequent cooling is provided by the substrate and martensite is formed. Stress relief heat treatment of the material immediately after welding tempers the martensite and eliminates any undesirable residual stresses.

6.0 RECOMMENDATIONS:


Control of interpass and bulk temperatures of cast steel pistons is critical to the success when GMAW bearing materials to heat treated steel pistons. Although GMAW procedures developed in this program are cost competitive, the rate of deposition, with attendant cost reduction, could be increased significantly by developing procedures to use larger diameter welding wire.

7.0 FUTURE WORK:

During the second phase of this program additional clad steel pistons will be manufactured for field tests. GMAW procedures using larger diameter wire will be investigated. Other cladding processes using strip welding and explosive bonding methods will be evaluated to determine the least-cost manufacturing method. An Engineering Change Proposal will be submitted to recommend implementation of the selected cladding process in production.



NOTE : DIM A = .60 THICKNESS AL-BRONZE OVERLAY
(a)



NOTE: ALL DIMENSIONS IN INCHES

FIGURE 1. FRICTION & WEAR TEST SPECIMENS.
a. BEARING DISC b. MATING STEEL RING




FIGURE 2. SHOWING WEAR ON SURFACES AFTER ONE-HOUR TESTS.
(a) NODULAR IRON VS. STEEL (b) AL-BRONZE OVERLAY VS. STEEL





FIGURE 3. DIMENSIONS FOR SHEAR AND TENSILE TEST SPECIMENS.



(a)




(b)

FIGURE 4. SPECIMENS BEFORE AND AFTER TESTS - (a) TENSILE TEST; (b) SHEAR TEST



(a)



(b)

FIGURE 5. MICROGRAPHS SHOWING COPPER-RICH DENDRITES IN
Al-BRONZE OVERLAY. MAG.: a. 100X b. 800X, ETCHANT:
 $\text{NH}_4\text{OH} - \text{H}_2\text{O}_2$ (1:1)




FIGURE 6. HEAT AFFECTED ZONE CONSISTS OF BAINITE AND FERRITE STRUCTURES. MAG.: 800X, ETCHANT: 2% Nital




FIGURE 7. CROSS SECTIONAL VIEW OF RECOIL PISTON FOR M174 GUN MOUNT, COATED WITH BEARING MATERIAL.






Figure 8. OVERALL SET UP FOR OVERLAYING AL-BRONZE ON M174 RECOIL PISTON USING GMAW PROCESS



b. OUTER DIAMETER



a. INNER DIAMETER

Figure 9. ILLUSTRATION OF TORCH POSITION LOOKING FROM REAR OF PISTON.



FIGURE 10. M174 PISTON COATED WITH AI-BRONZE (UNFINISHED).




FIGURE 11. CROSS SECTIONAL VIEW OF M174 PISTON, COATED WITH AL-BRONZE ON O.D. AND I.D. SURFACES.



FIGURE 12. LIGHT SCORING ON OUTER BEARING SURFACE OF M174 PISTON
AFTER TEST FIRING.



FIGURE 13. LIGHT SCORING ON INNER BEARING SURFACE OF M174 PISTON
AFTER TEST FIRING.




FIGURE 14. LINEAR SCRATCHES ON CHROMIUM PLATED SURFACE OF RECOIL CYLINDER AFTER TEST FIRING.

DISTRIBUTION

Copies

A. Department of Defense

Defense Documentation Center
ATTN: TIPDR
Cameron Station
Alexandria, VA 22314

12

B. Department of the Army

Commander
US Army Materiel Development and Readiness Command
ATTN: DRCMT
5001 Eisenhower Avenue
Alexandria, VA 22333

1

Commander
US Army Materiel Development and Readiness Command
Scientific and Technical Information Team - Europe
ATTN: DRXST-STL, Dr. Richard B. Griffin
APO New York 09710

1

Commander
US Army Armament Materiel Readiness Command
ATTN: DRSAR-RDP
DRSAR-SC
DRSAR-QAE
DRSAR-IRW
Rock Island, IL 61299

1

1

1

Commander
US Army Armament Research & Development Command
ATTN: DRDAR-PMP, Mr. Donald J. Fischer
Dover, NJ 07801

1

Director
US Army Materials and Mechanics Research Center
ATTN: DRXMR-M
Watertown, MA 02172

2

Commander
US Army Maintenance Management Center
ATTN: DRXMD-A
Lexington, KY 40507

1

Commander
US Army Electronics Research and Development Command
ATTN: DRSEL-PA-E
Fort Monmouth, NJ 07703

1

DISTRIBUTION

Copies

A. Department of Defense

Defense Documentation Center
ATTN: TIPDR
Cameron Station
Alexandria, VA 22314

12

B. Department of the Army

Commander
US Army Materiel Development and Readiness Command
ATTN: DRCMT
5001 Eisenhower Avenue
Alexandria, VA 22333

1

Commander
US Army Materiel Development and Readiness Command
Scientific and Technical Information Team - Europe
ATTN: DRXST-STL, Dr. Richard B. Griffin
APO New York 09710

1

Commander
US Army Armament Materiel Readiness Command
ATTN: DRSAR-RDP
DRSAR-SC
DRSAR-QAE
DRSAR-IRW
Rock Island, IL 61299

1

Commander
US Army Armament Research & Development Command
ATTN: DRDAR-PMP, Mr. Donald J. Fischer
Dover, NJ 07801

1

Director
US Army Materials and Mechanics Research Center
ATTN: DRXMR-M
Watertown, MA 02172

2

Commander
US Army Maintenance Management Center
ATTN: DRXMD-A
Lexington, KY 40507

1

Commander
US Army Electronics Research and Development Command
ATTN: DRSEL-PA-E
Fort Monmouth, NJ 07703

1

DISTRIBUTION

Copies

Commander
US Army Missile Research and Development Command
ATTN: DRDMI
Redstone Arsenal, AL 35809 1

Commander
US Army Tank-Automotive Materiel Readiness Command
ATTN: DRSTA-Q
Warren, MI 48090 1

Commander
US Army Tank-Automotive Research and Development Command
ATTN: DRDAR-UL
DRDTA-RKA
Warren, MI 48090 1 1

Commander
US Army Aviation Research and Development Command
ATTN: DRDAV-EXT
P.O. Box 209
St. Louis, MO 63166 1

Commander
US Army Troop Support and Aviation Materiel Readiness Command
ATTN: DRSTS-PLE
4300 Goodfellow Blvd.
St. Louis, MO 63120 1

Commander
Ballistic Research Laboratories
ATTN: DRXBR-X
Aberdeen Proving Ground, MD 21005 1

Commander
Harry Diamond Laboratories
ATTN: DRXDO-RCD
2800 Powder Mill Road
Adelphi, MD 20783 1

Commander
New Cumberland Army Depot
ATTN: SDSNC-QA
New Cumberland, PA 17070 1

Commander
Pueblo Army Depot Activity
ATTN: DRXPU
Pueblo, CO 81001 1

DISTRIBUTION

Copies

Commander
Red River Army Depot
ATTN: SDSRR-QA
Texarkana, TX 75501

1

Commander
Sacramento Army Depot
ATTN: SDSAA-QA
Sacramento, CA 95813

1

Commander
Seneca Army Depot
ATTN: SDSSE-R
Romulus, NY 14541

1

Commander
Sharpe Army Depot
ATTN: SDSSE-QE
Lathrop, CA 95330

1

Commander
Sierra Army Depot
ATTN: SDSSE-DQA
Merlong, CA 96113

1

Commander
Tobyhanna Army Depot
ATTN: SDSTO-Q
Tobyhanna, PA 18466

1

Director
US Army Industrial Base Engineering Activity
ATTN: DRXIB-MT
Rock Island Arsenal
Rock Island, IL 61299

2

Director
USDARCOM Intern Training Center
ATTN: SDSRR-QA
Red River Army Depot
Texarkana, TX 75501

1

Commander
US Army Tropic Test Center
ATTN: STETC-TD
Drawer 942
Fort Clayton, Canal Zone

1

DISTRIBUTION

Copies

Commander
Anniston Army Depot
ATTN: SDSAN-QA
Anniston, AL 36202

1

Commander
Corpus Christi Army Depot
ATTN: SDSCC-MEE
Mail Stop 55
Corpus Christi, TX 78419

1

Commander
Fort Wingate Army Depot Activity
ATTN: DRXFW
Gallup, NM 87301

1

Commander
Letterkenny Army Depot
ATTN: SDSLE
Chambersburg, PA 17201

1

Commander
Lexington-Blue Grass Army Depot Activity
ATTN: SOSLX
Lexington, KY 40507

1

Commander
Tooele Army Depot
ATTN: SDSTE-QA
Tooele, UT 84074

1

Commander
Holston Army Ammunition Plant
ATTN: SARHO
Kingsport, TN 37660

1

Commander
Indiana Army Ammunition Plant
ATTN: SARIN
Charleston, IN 47111

1

Commander
Iowa Army Ammunition Plant
ATTN: SARIO
Middletown, IA 52601

1

DISTRIBUTION

Copies

Commander Joliet Army Ammunition Plant ATTN: SARJO Joliet, IL 60434	1
Commander Lone Star Army Ammunition Plant ATTN: SARLS Texarkana, TX 75501	1
Commander Louisiana Army Ammunition Plant ATTN: SARLA P.O. Box 30058 Shreveport, LA 71161	1
Commander Milan Army Ammunition Plant ATTN: SARMI Milan, TN 38358	1
Commander Radford Army Ammunition Plant ATTN: SARRA Radford, VA 24141	1
Commander Riverbank Army Ammunition Plant ATTN: SARRB Riverbank, CA 95367	1
Commander Scranton Army Ammunition Plant ATTN: SARSC Scranton, PA 18501	1
Commander Twin Cities Army Ammunition Plant ATTN: SARTC New Brighton, MN 55112	1
Commander Volunteer Army Ammunition Plant ATTN: SARVO-T P.O. Box 6008 Chattanooga, TN 37401	1

DISTRIBUTION

Copies

C. Department of the Navy

Commander
US Navy Materiel Industrial Resources Office
ATTN: Code 044, CPT L. C. Dictmar
Code 227
Philadelphia, PA 19112

1
1

D. Department of the Air Force

Commander
Air Force Materials Laboratory
ATTN: LTM
Wright-Patterson AFB, OH 45433

1

DISTRIBUTION LIST UPDATE

- - - FOR YOUR CONVENIENCE - - -

Government regulations require the maintenance of up-to-date distribution lists for technical reports. This form is provided for your convenience to indicate necessary changes or corrections.

If a change in our mailing lists should be made, please check the appropriate boxes below. For changes or corrections, show old address exactly as it appeared on the mailing label. Fold on dotted lines, tape or staple the lower edge together, and mail.

Remove Name From List

Old Address:

Change or Correct Address

Corrected or New Address:

COMMENTS

Date: _____ Signature: _____

Technical Report #

FOLD HERE

Return Address:

POSTAGE AND FEES PAID
DEPARTMENT OF THE ARMY
DOD 314



OFFICIAL BUSINESS
Penalty for Private Use \$300

Commander
Rock Island Arsenal
Attn: SARRI-ENM
Rock Island, Illinois 61299

FOLD HERE

AD	Accession No.	UNCLASSIFIED	AD	Accession No.	UNCLASSIFIED
Commander, Rock Island Arsenal ATTN: SARRI-EN Rock Island, IL 61299	COATING OF STEEL PISTONS WITH BEARING MATERIAL (Phase 1), by Mukesh Solanki	1. Modular Iron 2. Steel 3. Al-Bronze 4. Toughness 5. GMAW 6. Wear	Commander, Rock Island Arsenal ATTN: SARRI-EN Rock Island, IL 61299	COATING OF STEEL PISTONS WITH BEARING MATERIAL (Phase 1), by Mukesh Solanki	1. Modular Iron 2. Steel 3. Al-Bronze 4. Toughness 5. GMAW 6. Wear
Report EN-81-01, Oct 80, 29 p. incl. illus., tables, (AMS Code 4932.06.8035) Unclassified Report.	Report EN-81-01, Oct 80, 29 p. incl. illus., tables, (AMS Code 4932.06.8035) Unclassified Report.	Modular iron pistons for the M174 Recoil Mechanism characteristically yield less-than-desirable service lives; the deficiency being attributed to a lack of fracture toughness of the iron. Consequently, cast steel pistons clad with a bearing material, required since the steel does not offer the built-in lubricity indigenous to modular iron, were considered as an alternate material.	Modular iron pistons for the M174 Recoil Mechanism characteristically yield less-than-desirable service lives; the deficiency being attributed to a lack of fracture toughness of the iron. Consequently, cast steel pistons clad with a bearing material, required since the steel does not offer the built-in lubricity indigenous to modular iron, were considered as an alternate material.	DISTRIBUTION Copies available from DDC	DISTRIBUTION Copies available from DDC
Commander, Rock Island Arsenal ATTN: SARRI-EN Rock Island, IL 61299	COATING OF STEEL PISTONS WITH BEARING MATERIAL (Phase 1), by Mukesh Solanki	1. Modular Iron 2. Steel 3. Al-Bronze 4. Toughness 5. GMAW 6. Wear	Commander, Rock Island Arsenal ATTN: SARRI-EN Rock Island, IL 61299	COATING OF STEEL PISTONS WITH BEARING MATERIAL (Phase 1), by Mukesh Solanki	1. Modular Iron 2. Steel 3. Al-Bronze 4. Toughness 5. GMAW 6. Wear
Report EN-81-01, Oct 80, 29 p. incl. illus., tables, (AMS Code 4932.06.8035) Unclassified Report.	Report EN-81-01, Oct 80, 29 p. incl. illus., tables, (AMS Code 4932.06.8035) Unclassified Report.	Modular iron pistons for the M174 Recoil Mechanism characteristically yield less-than-desirable service lives; the deficiency being attributed to a lack of fracture toughness of the iron. Consequently, cast steel pistons clad with a bearing material, required since the steel does not offer the built-in lubricity indigenous to modular iron, were considered as an alternate material.	Modular iron pistons for the M174 Recoil Mechanism characteristically yield less-than-desirable service lives; the deficiency being attributed to a lack of fracture toughness of the iron. Consequently, cast steel pistons clad with a bearing material, required since the steel does not offer the built-in lubricity indigenous to modular iron, were considered as an alternate material.	DISTRIBUTION Copies available from DDC	DISTRIBUTION Copies available from DDC

Cost-effective Gas Metal Arc Welding (GMAW) processing techniques were developed to provide an aluminum-bronze bearing surface to the steel pistons. Concurrent laboratory tests were conducted on welded specimens to simulate live-firing performance. The tests included chemical, mechanical and metallurgical analyses. After development of the GMAW procedure, including selection of an aluminum-bronze bearing material, a coated steel piston was manufactured at Rock Island Arsenal and subjected to firing tests. Its performance in the Arsenal simulator followed by live-firing at Yuma Proving Ground exceeded all requirements.

Future studies will provide more clad steel pistons for firing tests to verify material performance. In addition, strip welding and explosive bonding methods will be evaluated to determine the least cost method of cladding steel components with aluminum-bronze.

Cost-effective Gas Metal Arc Welding (GMAW) processing techniques were developed to provide an aluminum-bronze bearing surface to the steel pistons. Concurrent laboratory tests were conducted on welded specimens to simulate live-firing performance. The tests included chemical, mechanical and metallurgical analyses. After development of the GMAW procedure, including selection of an aluminum-bronze bearing material, a coated steel piston was manufactured at Rock Island Arsenal and subjected to firing tests. Its performance in the Arsenal simulator followed by live-firing at Yuma Proving Ground exceeded all requirements.

Future studies will provide more clad steel pistons for firing tests to verify material performance. In addition, strip welding and explosive bonding methods will be evaluated to determine the least cost method of cladding steel components with aluminum-bronze.

Cost-effective Gas Metal Arc Welding (GMAW) processing techniques were developed to provide an aluminum-bronze bearing surface to the steel pistons. Concurrent laboratory tests were conducted on welded specimens to simulate live-firing performance. The tests included chemical, mechanical and metallurgical analyses. After development of the GMAW procedure, including selection of an aluminum-bronze bearing material, a coated steel piston was manufactured at Rock Island Arsenal and subjected to firing tests. Its performance in the Arsenal simulator followed by live-firing at Yuma Proving Ground exceeded all requirements.

Future studies will provide more clad steel pistons for firing tests to verify material performance. In addition, strip welding and explosive bonding methods will be evaluated to determine the least cost method of cladding steel components with aluminum-bronze.

Cost-effective Gas Metal Arc Welding (GMAW) processing techniques were developed to provide an aluminum-bronze bearing surface to the steel pistons. Concurrent laboratory tests were conducted on welded specimens to simulate live-firing performance. The tests included chemical, mechanical and metallurgical analyses. After development of the GMAW procedure, including selection of an aluminum-bronze bearing material, a coated steel piston was manufactured at Rock Island Arsenal and subjected to firing tests. Its performance in the Arsenal simulator followed by live-firing at Yuma Proving Ground exceeded all requirements.

Future studies will provide more clad steel pistons for firing tests to verify material performance. In addition, strip welding and explosive bonding methods will be evaluated to determine the least cost method of cladding steel components with aluminum-bronze.

AD	Accession No.	UNCLASSIFIED	Accession No.	UNCLASSIFIED
	Commander, Rock Island Arsenal ATTN: SARRI-EN Rock Island, IL 61299	1. Modular Iron 2. Steel 3. Al-Bronze 4. Toughness 5. GMAW 6. Wear	Commander, Rock Island Arsenal ATTN: SARRI-EN Rock Island, IL 61299 COATING OF STEEL PISTONS WITH BEARING MATERIAL (Phase 1), by Mukesh Solanki	1. Modular Iron 2. Steel 3. Al-Bronze 4. Toughness 5. GMAW 6. Wear
	Report EN-81-01, Oct 80, 29 p. incl. illus., tables, (AMS Code 4932.06.8035) Unclassified Report.	Modular Iron pistons for the M174 Recoil Mechanism characteristically yield less-than-desirable service lives; the deficiency being attributed to a lack of fracture toughness of the iron. Consequently, cast steel pistons clad with a bearing material, required since the steel does not offer the built-in lubricity indigenous to modular iron, were considered as an alternate material.	Report EN-81-01, Oct 80, 29 p. incl. illus., tables, (AMS Code 4932.06.8035) Unclassified Report.	Modular Iron pistons for the M174 Recoil Mechanism characteristically yield less-than-desirable service lives; the deficiency being attributed to a lack of fracture toughness of the iron. Consequently, cast steel pistons clad with a bearing material, required since the steel does not offer the built-in lubricity indigenous to modular iron, were considered as an alternate material.
		DISTRIBUTION Copies available from DDC	DISTRIBUTION Copies available from DDC	DISTRIBUTION Copies available from DDC
AD	Accession No.	UNCLASSIFIED	Accession No.	UNCLASSIFIED
	Commander, Rock Island Arsenal ATTN: SARRI-EN Rock Island, IL 61299	1. Modular Iron 2. Steel 3. Al-Bronze 4. Toughness 5. GMAW 6. Wear	Commander, Rock Island Arsenal ATTN: SARRI-EN Rock Island, IL 61299 COATING OF STEEL PISTONS WITH BEARING MATERIAL (Phase 1), by Mukesh Solanki	1. Modular Iron 2. Steel 3. Al-Bronze 4. Toughness 5. GMAW 6. Wear
	Report EN-81-01, Oct 80, 29 p. incl. illus., tables, (AMS Code 4932.06.8035) Unclassified Report.	Modular Iron pistons for the M174 Recoil Mechanism characteristically yield less-than-desirable service lives; the deficiency being attributed to a lack of fracture toughness of the iron. Consequently, cast steel pistons clad with a bearing material, required since the steel does not offer the built-in lubricity indigenous to modular iron, were considered as an alternate material.	Report EN-81-01, Oct 80, 29 p. incl. illus., tables, (AMS Code 4932.06.8035) Unclassified Report.	Modular Iron pistons for the M174 Recoil Mechanism characteristically yield less-than-desirable service lives; the deficiency being attributed to a lack of fracture toughness of the iron. Consequently, cast steel pistons clad with a bearing material, required since the steel does not offer the built-in lubricity indigenous to modular iron, were considered as an alternate material.
		DISTRIBUTION Copies available from DDC	DISTRIBUTION Copies available from DDC	DISTRIBUTION Copies available from DDC

Cost-effective Gas Metal Arc Welding (GMAW) processing techniques were developed to provide an aluminum-bronze bearing surface to the steel pistons. Concurrent laboratory tests were conducted on welded specimens to simulate live-firing performance. The tests included chemical, mechanical and metallurgical analyses. After development of the GMAW procedure, including selection of an aluminum-bronze bearing material, a coated steel piston was manufactured at Rock Island Arsenal and subjected to firing tests. Its performance in the Arsenal simulator followed by live-firing at Yuma Proving Ground exceeded all requirements.

Future studies will provide more clad steel pistons for firing tests to verify material performance. In addition, strip welding and explosive bonding methods will be evaluated to determine the least cost method of cladding steel components with aluminum-bronze.

Cost-effective Gas Metal Arc Welding (GMAW) processing techniques were developed to provide an aluminum-bronze bearing surface to the steel pistons. Concurrent laboratory tests were conducted on welded specimens to simulate live-firing performance. The tests included chemical, mechanical and metallurgical analyses. After development of the GMAW procedure, including selection of an aluminum-bronze bearing material, a coated steel piston was manufactured at Rock Island Arsenal and subjected to firing tests. Its performance in the Arsenal simulator followed by live-firing at Yuma Proving Ground exceeded all requirements.

Future studies will provide more clad steel pistons for firing tests to verify material performance. In addition, strip welding and explosive bonding methods will be evaluated to determine the least cost method of cladding steel components with aluminum-bronze.

Cost-effective Gas Metal Arc Welding (GMAW) processing techniques were developed to provide an aluminum-bronze bearing surface to the steel pistons. Concurrent laboratory tests were conducted on welded specimens to simulate live-firing performance. The tests included chemical, mechanical and metallurgical analyses. After development of the GMAW procedure, including selection of an aluminum-bronze bearing material, a coated steel piston was manufactured at Rock Island Arsenal and subjected to firing tests. Its performance in the Arsenal simulator followed by live-firing at Yuma Proving Ground exceeded all requirements.

Future studies will provide more clad steel pistons for firing tests to verify material performance. In addition, strip welding and explosive bonding methods will be evaluated to determine the least cost method of cladding steel components with aluminum-bronze.

Cost-effective Gas Metal Arc Welding (GMAW) processing techniques were developed to provide an aluminum-bronze bearing surface to the steel pistons. Concurrent laboratory tests were conducted on welded specimens to simulate live-firing performance. The tests included chemical, mechanical and metallurgical analyses. After development of the GMAW procedure, including selection of an aluminum-bronze bearing material, a coated steel piston was manufactured at Rock Island Arsenal and subjected to firing tests. Its performance in the Arsenal simulator followed by live-firing at Yuma Proving Ground exceeded all requirements.

Future studies will provide more clad steel pistons for firing tests to verify material performance. In addition, strip welding and explosive bonding methods will be evaluated to determine the least cost method of cladding steel components with aluminum-bronze.

